

# SGS Testing Korea Co., Ltd.

#1002-2, Hwasan-ri, Onsan-ub, Ulju-gun, Ulsan, Korea 689-890  
Tel : 052)239-6908~10, Fax: 052)239-6913, InterNet>http://www.sgslab.co.kr

## Test Report

No. F690501/LF-CTS058085

Date : June 29, 2005


Page 1 of 2

KOREA KUMHO PETROCHEMICAL CO., LTD.  
680, Sangkae-dong, Nam-ku,  
Ulsan, Korea

The following merchandise was submitted and identified by the client as : -

Type of Product : KOSYN RM 21  
SGS File No. : P-48/2005-0590/1  
Materials : Synthetic Rubber  
Sample Receiving Date : Jun. 22, 2005  
Test Performing Date : Jun. 23, 2005  
Test Performed : SGS Testing Korea tested the sample which was selected by applicant with following result.  
Test Results : For further details, please refer to following page.

SGS Testing Korea Co., Ltd.



Thomas Hwang / Lab. Manager

SBP/mss

# SGS Testing Korea Co., Ltd.

#1002-2, Hwasan-ri, Onsan-ub, Ulju-gun, Ulsan, Korea 689-890  
Tel : 052)239-6908~10, Fax: 052)239-6913, InterNet>http://www.sgslab.co.kr

## Test Report

No. F690501/LF-CTS058085

Date : June 29, 2005

Page 2 of 2

### Heavy Metal

Test Item	Unit	Test Method	MDL	Result
Cadmium (Cd)	mg/kg	ISO 6101-2, ICP-AES	0.5	n. d.
Lead (Pb)	mg/kg	ISO 6101-2, ICP-AES	10	n. d.
Mercury (Hg)	mg/kg	USEPA 3052, ICP-AES	2	n. d.
Hexavalent Chromium (Cr VI)	mg/kg	DIN 53314, UV-Vis	0.5	n. d.

Note (1) n. d. = Not detected  
(2) MDL = Method Detection Limit

\*\*\*\*\* END \*\*\*\*\*